

Wheel Index Vehicle History Check Report



Summary

Vehicle	2014 KIA Sportage 2.0
Mileage	80,000 km *based on average car mileage of 20 000km driven per year.
Condition	GOOD
Accident Count	1
Current Finance Bank/House	Not financed
Theft Status	CLEAR - no issues
Trade-In Value	R199,000
Retail Value	R254,800

Specifications

i Does the car description below match the details on the logbook/registration papers? If not, you should query the discrepancy with the seller if you intend to buy the car.

Year	2014
VIN	KNAPC81ALE7601312

Engine Number	G4NAEU269692
Make	KIA
Model	KIA Sportage
Full Name	Sportage 2.0
Colour (original)	DARK SILVER
Body Type	SUV
Transmission	Manual
Propulsion	Petrol
Engine Displacement	2 litres
Power	116 kw
Cylinders	4
Doors	5
Kerb Mass:	1380 kg
Introduction Month:	February 2014
Discontinuation Month:	Not Available
Warranty start year	2014
Warranty start quarter	1
Warranty period	5 Years / 150 000 km
Service plan period	5 Years / 100 000 km
Maintenance plan period	Optional Years / Optional km
Servicing intervals	15 000 km

Finance Status

i The bank owns the car until the loan is fully repaid if the car is still under a finance agreement.

Finance Bank/House	Not financed
Finance contract start date	Not Available
Finance contract end date	Not Available
Finance account number	Not Available

Accident Repair History

i Even though the data we show is comprehensive, the fact that a record of a accident repair is not returned by the system doesn't mean that it hasn't been in an accident or been repaired; it may have been repaired by a smaller or non-approved repairer.

Date	City	Licence No
22 November 2016	Klerksdorp	CJN811NW

SAPS Interest (theft status)

i Wheel Index provides information from the South African Police Service national vehicle database on the status of wanted/stolen vehicles. These vehicles remain the property of the individual or organisation from whom they were taken. Never buy a vehicle that is flagged on this register, you stand to lose it, together with all the money you paid for it.

CLEAR - no issues

Microdot Information

i MicroDot technology is a highly effective form of vehicle marking, it involves spraying thousands of the small dots laser etched with a unique PIN.

MicroDot fitted	Yes
MicroDot fitment date	18 February 2014
MicroDot pin	KNAPC81ALE7601312

Retail Values

i This amount refers to the price consumers will pay when buying a car from a car dealership.

Retail Estimated Value:

R254,800

Retail Estimated Low Value:

R229,100

Retail Estimated High Value:

R283,400

Trade Values

i This is the price a car dealership will pay to buy a used car as stock or Trade-In.

Trade Estimated Value:

R221,400

Trade Estimated Low Value:

R199,000

Trade Estimated High Value:

R246,200

Auction Value

i This amount refers to the estimated sale price when buying a car from a public auction.

Auction Estimated Value:

R178,500

Price people are paying

i For similar Make, Model, and Year as this car

Sale Date	Licensing District	Sale Price
22 October 2018	BREEDE VALLEY	R239,990
31 August 2018	//KHARA HAIS	R245,995
14 August 2018	CITY OF TSHWANE	R259,900
09 May 2018	EMFULENI	R251,950
27 March 2018	CITY OF TSHWANE	R249,900

Contact Info:

Email: support@wheelindex.co.za

Company:

Full Name: Wheel Index (PTY)

Address: 1st Floor, Block B & Block C, Metropolitan Park, 8 Hillside Road, Parktown, Johannesburg

Registration Number: 2015/410031/07

Website: www.wheelindex.co.za